

August 17, 2018

Product Discontinuance Notification

Products Affected: PSV124-1F, PSV154-1F, PSV474-1F, PSV684-1F, PSV105-1F, PV124-3F, PV154-1F, PV474-1F, PV684-1F, PV105-1F, PVW124-3F, PVW154-3F, PVW474-1F, PVW684-1F, PVW105-1F, PKV124-3F, PKV154-1F, PKV474-1F, PKV684-1F, PKV105-1F, B124-3F-01, B474-3F-01, B684-1F-01, B105-1F-01, G124-3F, G474-1F, G684-1F, G105-1F, ST124-3F, ST474-3F, ST684-1F, ST105-1F, TT124-3F-01, TT474-3F-01, TT684-1F-01, TT105-1F-01

Effective Date: August 17, 2018

Reason for Discontinuance:

Piconics is unable to procure the appropriate ferrite core material for these particular inductor.

Last Time Buy:

Piconics is unable to offer a last time buy for these products due to the inability to procure the correct ferrite core material required to manufacture the product.

Suggested Replacement:

Piconics is unable to offer a replacement at this time

Piconics apologizes for any inconvenience this has caused. Please feel free to contact us with any questions or concerns. Thank you.

Sincerely,

-Piconics Management